



AIRCRAFT ACCIDENT REPORT SI 05/15

**Air Accident Investigation Bureau
Ministry of Transport, Malaysia**

**Final Report on the Serious Incident involving
Fixed wing aircraft ATR72-600 Registration 9M-LMG
in Penang, Malaysia on 28th May 2015**



INTRODUCTION

The Air Accident Investigation Bureau of Malaysia

The Air Accident Investigation Bureau of Malaysia (AAIB) is the air accidents and serious incidents investigation authority in Malaysia and is responsible to the Minister of Transport. Its mission is to promote aviation safety through the conduct of independent and objective investigation into air accidents and serious incidents.

The AAIB conducts the investigations in accordance with Annex 13 to the Chicago Convention and Civil Aviation Regulations of Malaysia 2016.

In carrying out the investigations, the AAIB will adhere to ICAO's stated objective, which is as follows:

“The sole objective of the investigation of an accident or incident shall be the prevention of accidents and incidents. It is not the purpose of this activity to apportion blame or liability”.

Accordingly, it is inappropriate that AAIB reports should be used to assign fault or blame or determine liability, since neither the investigation nor the reporting process has been undertaken for that purpose.

AIRCRAFT SERIOUS INCIDENT REPORT SI 05/15

| | | |
|--------------------------------------|----------|---|
| Aircraft Type | : | ATR72-600 |
| Model | : | ATR72-212A |
| Owner | : | Malindo Air |
| Nationality | : | Malaysia |
| Year of Manufacture | : | 2013 |
| Aircraft Registration | : | 9M-LMG |
| Serial Number | : | 1089 |
| State of Registration | : | Malaysia |
| State of Operator | : | Malaysia |
| Place and State of Occurrence | : | Penang International Airport, Penang, Malaysia |
| Date and Time of Occurrence | : | 28.05.2015 1317hrs (LT) |

All times in this report are Local Time (LT) (UTC +8 hours)

TABLE OF CONTENTS

| | |
|--|----------|
| SYNOPSIS..... | 1 |
| 1.0 FACTUAL INFORMATION | |
| 1.1 History of the flight..... | 1 |
| 1.2 Injuries to persons..... | 1 |
| 1.3 Damage to aircraft..... | 1 |
| 1.4 Other damage..... | 1 |
| 1.5 Personal Information..... | 2 |
| 1.6 Aircraft Information..... | 2 |
| 1.7 Meteorological Information..... | 3 |
| 1.8 Aids to navigation..... | 3 |
| 1.9 Communications..... | 3 |
| 1.10 Aerodrome information..... | 3 |
| 1.11 Flight Recorders..... | 3 |
| 1.12 Wreckage and impact information..... | 3 |
| 1.13 Medical and pathological information..... | 3 |
| 1.14 Fire..... | 4 |
| 1.15 Survival aspects..... | 4 |
| 1.16 Tests and research..... | 4 |
| 1.17 Organisational and management information..... | 4 |
| 1.18 Additional information..... | 4 |
| 1.19 Useful or effective investigation techniques..... | 4 |
| 2.0 ANALYSIS..... | 4 |
| 3.0 CONCLUSIONS..... | 5 |
| 3.1 Findings..... | 5 |
| 3.2 Probable Cause..... | 5 |
| 4.0 SAFETY RECOMMENDATIONS..... | 5 |
| 5.0 APPENDICES..... | 6 |
| Engine fire preliminary field inspection report..... | 6 |
| Certificate of Registration..... | 16 |
| Certificate of Airworthiness..... | 17 |
| Air Operator Certificate..... | 18 |
| Lion Air B-Nut Presentation..... | 19 |
| Pratt & Whitney Service Information Letter..... | 34 |
| Malindo Air Quality Notice..... | 36 |

SYNOPSIS

On the 28th May 2015, an ATR72-212A aircraft operated by Malindo Air bearing registration 9M-LMG with a flight number OD1165 departed out of Penang International Airport, Penang (PEN) en-route to Sultan Abdul Aziz Shah International Airport, Subang (SZB).

After take-off from PEN, the aircraft suffered a No. 01 engine fire. Procedures were carried out by the operating crew and after the procedures completed the aircraft returned to the airport and landed safely.

1.0 FACTUAL INFORMATION

1.1 History of the flight

On the 28th May 2015 at approximately 1317hrs (LT), an ATR72-212A aircraft en-route from PEN to SZB with registration number 9M-LMG bearing flight number OD1165 operated by Malindo Air suffered an in-flight external engine fire after take-off.

After flap retraction climbing passing approximately 800 feet, engine fire warning came on EWD. The flight crew carried out all the required procedures, discharged both fire extinguishers and requested for air turn back to PEN.

The aircraft safely landed at the airport. At landing it has been confirmed that there was no fire anymore. There were no passengers on board and the crew members disembarked safely with no injuries.

1.2 Injuries to persons

| Injuries | Crew | Passengers | Others |
|------------|------|------------|--------|
| Fatal | Nil | Nil | Nil |
| Serious | Nil | Nil | Nil |
| Minor/None | 04 | Nil | Nil |

1.3 Damage to aircraft

Please refer Attachments.

1.4 Other damage

Nil.

1.5 Personal Information

15.1 Captain

| | |
|---------------------|---|
| Status | Commander |
| Nationality | Malaysian |
| Age | 28 Years old |
| Gender | Male |
| Licence Type | CPL/ATPL 4202 |
| Licence Validity | Valid until 29 th February 2016 |
| Medical Examination | February 2016 |
| Aircraft Rating | ATR72-600 |
| Certificate of Test | 07 th July 2015 |
| Instructor Rating | Nil |
| Flying Hours | Total hours : 852:59hrs Total on type : 4148:45hrs |

15.2 Co-pilot

| | |
|---------------------|--|
| Status | Second Officer |
| Nationality | Malaysia |
| Age | 27 Years old |
| Gender | Male |
| Licence Type | CPL 4880 |
| Licence Validity | Valid until 30 th September 2015 |
| Medical Examination | 30 th September 2015 |
| Aircraft Rating | ATR72-600 |
| Certificate of Test | 02 nd August 2015 |
| Instructor Rating | Nil |
| Flying Hours | Total hours : 457:53hrs Total on type : 257:53hrs |

1.6 Aircraft Information

| | |
|---------------------------|------------------------------|
| Aircraft | ATR72-600 |
| Owner | Malindo Air |
| Registration | 9M-LMG |
| Serial No. | 1089 |
| Air Operator Cert. expiry | 31 st August 2015 |
| CofA No. | M.1573 |
| CofA expiry | 29 th July 2015 |
| CofR No. | M.1810 |
| CofR expiry | N/A |

| | |
|---------------------|-----------|
| Year of manufacture | 2013 |
| Operations | Scheduled |
| Flight Hours | 4865 |
| Flight Cycles | 5569 |
| Engine type | PW127M |
| Engine Serial No. | ED0673 |
| Engine Total Time | 4865 |

1.7 Meteorological Information

The meteorological station reported the wind at 1300hrs (LT) as 200/08kts. The weather was clear and the visibility was 7km at the time of occurrence.

1.8 Aids to navigation

Not applicable.

1.9 Communications

Nil.

1.10 Aerodrome information

Nil.

1.11 Flight Recorders

The aircraft was fitted with L-3 COMM Flight Data Recorder (FDR) and Cockpit Voice Recorder (CVR).

1.12 Wreckage and impact information

Nil.

1.13 Medical and pathological information

Nil.

1.14 Fire

The aircraft had an in-flight external fire and both fire extinguishers were discharged. On landing it has been confirmed that fire had extinguished.

1.15 Survival aspects

Not applicable.

1.16 Tests and research

Please refer attachments.

1.17 Organisational and management information

Nil.

1.18 Additional information

Nil.

1.19 Useful or effective investigation techniques

Not applicable.

2.0 ANALYSIS

2.1 Aircraft operated out of SZB to PEN, and the flight was normal until it landed at PEN.

2.2 After landing in PEN, the Captain reported that the aircraft have radio failure that requires the aircraft to be grounded in PEN while waiting the rescue team to arrive and troubleshoot.

2.3 After troubleshooting, nil defect was found and the aircraft ready for reposition flight back to SZB.

2.4 Not long after take-off from PEN, no. 1 engine fire warning illuminated, the flight crew carried out all the necessary procedures and turn the aircraft back to PEN.

2.5 There was no injury to crew and passengers on board.

3.0 CONCLUSIONS

3.1 Findings

- a) The flight crew members were properly licensed, medically fit, well experienced and adequately rested prior to the flight.
- b) The aircraft was airworthy and within the validity of the AOC, CofA and CofR.
- c) Several parts of the right hand engine have been found damaged by the fire event.

3.2 Probable Cause

The probable cause of the engine fire is due to the fuel leak from No. 3 fuel nozzle manifold 'B' nut.

4.0 SAFETY RECOMMENDATIONS

(See Quality Notice MARA/QN/ATR72/16/04 dated 12 Feb 2016)

4.1 It is recommended that the manufacturer to remind customers of the importance to use the products recommended in the Engine Maintenance Manual (EMM).

4.2 It is recommended that the restoration of fuel nozzle for both engines on one aircraft shall not be performed at the same maintenance visit.

4.3 It is recommended that the engineer in-charge to perform a detailed inspection of the manifold hoses B-nut to ensure no early sign of corrosion is observed.

4.4 It is recommended that manifold with sign of corrosion shall be quarantined and reported to quality Assurance for further investigation.

4.5 It is recommended that the Licensed Engineer shall ensure that only approved solvent/materials listed in Maintenance Manual are to be used throughout the maintenance process.

5.0 APPENDICES

Appendix 1: Engine fire preliminary field inspection report

9M-LMG LH Engine Fire Preliminary Field Inspection Report Update 4/Final: at 03-June-2015

A. Detail of Event

Aircraft Registration : 9M-LMG
Engine Serial Number : ED0873
TSN : 4885 hours
CSN : 5589 cycles
Date of event : 28-May-2015

Based on Aircraft Flight and Maintenance Log (AFML) reference A023108 dated 28th May 2015, the aircraft was enroute to SZB on flight OD01165. Aircraft was turned back and landed at the origin 1338 (LT) uneventful. The discrepancy noted on the logbook was 'ENG NO 1 FIRE AFTER T/O. BOTH FIRE EXTINGUISHER DISCHARGED'.

AFML Number references (A023101 – A023108) were reviewed. Work summary was below:

C check was performed by Airod Sdn Bhd between 10th April 2015 and 27th May 2015.

AFML reference A023107 dated 28th May 2015, the aircraft departed on Malindo flight OD01164, from SZB to PEN, pilot reported with defect transponder #1 and #2 inoperative. Operational test carried out. No engine #1 related defect was reported on OD01164.

Malindo has informed that the last fuel nozzle change was performed on 4th April 2015 by Malindo dedicated fuel nozzle team. Post fuel nozzle change, the subject engine has flown 42 hours prior the C check.

B. Field Report and Observation



On site participants were below:

- 1) Aida Nazliha binti Samingan – Malaysia DCA Assistance Director Airworthiness Sector (email: aida.nazliha@dca.gov.my)
- 2) Aliham Abdullah – Malindo Quality Assurance Manager (email: aliham.abdullah@malindoair.com)
- 3) Kenneth Makunga – ATR Field Support Representative (email: kmakunga@galaviation.ca)
- 4) Chandra Gunawan – P&WC Customer Manager / Field Support Representative (email: chandra.gunawan@pwc.ca)
- 5) Lim Chee Ching – P&WC Field Support Representative (email: chee.ching.lim@pwc.ca)

Export Classification: **No technical data**





Page 1

Day 1: 29-May-2015

| Photo | Description |
|---|---|
|  | Burn mark observed on the aft cowling and panel on the underwing box. (LH View) |
|  | The rear RH cowl was delaminated. Observed sign of overheating on the inner pane. |
|  | Sign of burn mark on the engine harness near the fuel nozzle adapter #3 and #4. |

Export Classification: No technical data

Page 2

| Photo | Description |
|--|---|
| <p>Fuel Nozzle No. 3</p>  | <p><u>Step 1:</u> Nitrogen leak check at 150 psi and Snoop leak detector applied.</p> <p><u>Result:</u> All fuel nozzle connections (except fuel nozzle no. 3) to the primary and secondary fuel manifolds were verified and no bubbles were observed.</p> <p>Fuel nozzle no. 3 found with bubble leak at secondary manifold.</p> |
| <p>Fuel Nozzle No. 3</p>  | <p><u>Step 2:</u> Torque check using torque wrench PWC45200</p> <p><u>Result:</u> Found the B-nut able to turn more than 120 degree without much resistance. B-Nut was sheared.</p> |
| <p>Fuel Nozzle No. 3</p>  | <p>B-nut completely sheared.</p> |
| <p>Fuel Nozzle No. 3</p>  | <p><u>Step 3:</u> Review of <u>previous</u> photo prior to torque check.</p> <p><u>Result:</u> Found the B-Nut was already cracked.</p> |

Export Classification: No technical data

| Photo | Description |
|--|--|
| <p data-bbox="371 566 810 589"><u>Secondary manifold connected to fuel nozzle no. 3</u></p>  <p data-bbox="371 947 810 969"><u>Secondary manifold connected to fuel nozzle no. 3</u></p>  | <p data-bbox="882 589 1257 678">Secondary manifold attached to fuel nozzle no. 3, shown with B-nut sheared. Photo taken, after secondary manifold was removed at 02-June-15.</p> |
|  | <p data-bbox="882 1400 1121 1422">Inspect fuel nozzle #3 threads.</p> <p data-bbox="882 1444 1034 1489"><u>Result:</u> Threads are clean.</p> |

Export Classification: No technical data

Page 4

Day 2: 02-June-2015

Engine already removed and placed at working stand.

Prior engine removal, torque seal already applied at fuel nozzle B-nuts connection at 29-May-2015, approx. 5 pm.

At 02-June-2015, 04:00 engine removal completed. Torque dial indicator is also available on-site.




Personnel on-site:

Alham Abdullah (Manager QA, Malindo)

Hazwan Janai (Power plant, Technical Services)

Chandra Gunawan (CM/FSR, P&WC)

Kenneth Makunga (FSR, ATR)

| Photo | Description |
|---|---|
|  | Torque check using torque wrench PWC45200 (Phase-4 torque wrench). <u>Result:</u> All fuel nozzles, except fuel nozzle #4, the B-nut did not turn further when torque is applied. |
| <p>Fuel nozzle no. 4, before torque check</p>  | <u>Result:</u> Fuel nozzle #4 able to turn approx. 45 degrees in tightening direction. Note: during Nitrogen leak check with Snoop leak detector at 29-May, no bubbles were observed at fuel nozzle #4. |
| <p>Fuel nozzle no. 4, after torque check</p>  | |


Export Classification: No technical data

Page 5

| Photo | Description |
|---|--|
|  | <p>Inspect fuel nozzle no. 4 thread and secondary manifold B-nut thread connected to fuel nozzle no. 4</p> <p><u>Result:</u> Found black substance in the thread area of the flex manifold B-nut</p> <p><u>Result:</u> Found black substance in the thread area of the fuel nozzle no. 4</p> |
| | <p>With using torque wrench dial-indicator type, check break-away torque at B-nuts connection in loosening direction.</p> <p><u>Result:</u> The result varies from 180 lb. Inch to 220 lb. inch. None of fuel nozzles were over torqued.</p> |
|  | <p>Check flexible manifolds B-nut thread with go-and-no-go gauge (PWC45232)</p> <p><u>Result:</u> All threads (except at FNZ #3 secondary port, not possible to check) are able to engage with go-and-no-go tool smoothly.</p> |



Export Classification: No technical data

Page 6

| Photo | Description |
|--|--|
|  | <p>Inspect B-nuts threads at fuel manifolds for anti-seize presence.</p> <p><u>Result:</u> Found residual of black substance alike at the thread area.</p> |

Export Classification: No technical data

Page 7

| Photo | Description |
|--|---|
|  | <p>Inspect conical gaskets.</p> <p><u>Result:</u> Found conical gasket at manifold #14 with tangs bent. The rest of conical gaskets are good, including conical gasket connected at fuel nozzle #3.</p> |
|  | <p>Fuel nozzle #3, #4, and #5 ports.</p> |

Export Classification: No technical data

C. Parts Removed for Investigation

The following engine parts were removed and sent for investigation to P&WC Service Investigation, Canada.

- 1) Fuel Nozzle No. 3, P/N: 3079013-01, S/N: DEAAA30046
- 2) Fuel Nozzle No. 4, P/N: 3079012-01, S/N: DEAAA33052
- 3) Secondary Manifold Left, P/N: 3059765-01, S/N: 07518478-01
- 4) Secondary Manifold Right, P/N: 3059764-01, S/N: 07490965-01
- 5) Primary Manifold, P/N: 3059766-01, S/N: 07557710-01

D. Summary

This field report does not constitute nor replace the engine investigation which will be performed by P&WC Service Investigation.

The investigation report released by P&WC Service Investigation shall be the official and the final investigation report.

Based on the hardware witness on-site, the following findings were observed:

1. Fuel nozzle no. 3 found with leak during nitrogen leak check. Further inspection found with B-nut cracked and subsequently sheared during torque check.
2. Fuel nozzle no. 4 found with loose B-nut. During nitrogen leak check, no bubbles were observed.

Note: there are two steps of leak check in accordance with EMM. Step 1 is nitrogen leak check with leak detector; Step 2 is by running the engine at high power (80% torque) for 2 minutes. This two steps leak check is an integral part of leak check to be performed post fuel nozzle installation.

During this field observation, only Step 1 (nitrogen leak check) was performed.

E. Chronology and Progress Report

| Date | Description | Remarks |
|---------|---|---------|
| 28-May | Date of the event Malindo Team, ATR and FSR arrived on-site | |
| 29-May | Field report and observation started. DCA Malaysia arrived on-site | |
| 30-May | ATR requires engine to drop for NDT access. P&WC Preliminary field inspection report issued. To remove flex manifolds and FNZ #3 for investigation. | |
| 30-May | Malindo QA advised to hold engine works, pending for DCA Malaysia go-ahead. In evening, verbal info obtained to continue. | |
| 01-June | ATR Specialist arrived on-site and preliminary inspect the engine and airframe. Engine removal for access was requested for better access to airframe. Engine removal completion expected at 02-June-15. | |
| 02-June | Engine removal completed at 03-June, approx. 04 am. Engine located at working stand. Torque gauge dial indicator is available. | |
| 03-June | Engine field report and observation completed, accompanied by Malindo Manager QA. Flexible manifolds removed (primary, secondary left, and secondary right). Fuel nozzle #3 removed. Fuel nozzle #4 removed. Pending shipment to P&WC Service Investigation Canada. | |
| TBA | | |

Note:

Chronology and Progress Report will be carried forward separately from this report.

Prepared by,

Chandra Gunawan and Lim Chee Ching
Pratt & Whitney Canada

Date:



29-May-2015, Penang Malaysia (first report issuance)
03-June-2015, Penang Malaysia (this report)

Export Classification: **No technical data**

Page 10

Appendix 2: Certificate of Registration

(JPA 24L-Pin, 4/95)

| | | |
|---|--|--|
|  MALAYSIA JABATAN PENERBANGAN AWAM DEPARTMENT OF CIVIL AVIATION | | Nombor Perakuan Certificate Number M.1810 |
| PERAKUAN PENDAFTARAN KAPALUDARA CERTIFICATE OF REGISTRATION OF AIRCRAFT | | |
| Kenegaraan Dan Tanda Pendaftaran <i>Nationality And Registration Marks</i> 9M-LMG | Pembuat dan Nama Sebutan Kapaludara <i>Manufacturer and Manufacturer's Designation of Aircraft</i> ATR - GIE Avions de Transport Regional ATR 72-212 A | Nombor Siri Kapaludara <i>Aircraft Serial Number</i> 1089 |
| Nama dan Alamat Pemunya <i>Name and Address of Owner(s)</i> PHOENIX AVIATION 18 LIMITED P.O. BOX 1093, QUEENSGATE HOUSE GRAND CAYMAN, KY1-1102 CAYMAN ISLANDS | | |
| Nama dan Alamat Penyewa/Pencarter <i>Name and Address of Hire/Charterer</i> MALINDO AIRWAYS SDN. BHD. C-5-05, BLOCK C, OASIS ARA DAMANSARA 2 JALAN PJU 1A/7A, 47301 PETALING JAYA SELANGOR DARUL EHSAN, MALAYSIA | | |
| <p>Adalah dengan ini diperakui bahawa kapaludara yang diperihalkan di atas telah dimasukkan dalam Daftar Kapaludara menurut Konvensyen Penerbangan Awam Antarabangsa bertarikh 7 Disember 1944, dan Akta Penerbangan Awam 1968 dan peraturan-peraturan yang dikeluarkan di bawahnya.</p> <p><i>It is hereby certified that the above described aircraft has been duly entered on the Aircraft Register in accordance with the Convention on International Civil Aviation dated 7 December 1944, and with the Civil Aviation Act 1968 and regulations issued thereunder.</i></p> | | |
| Tarikh dikeluarkan <i>Date of Issue</i> 31-Mar-2014 | |  SUHANNA ABU HASSAN Ketua Pengarah Penerbangan Awam <i>Director General of Civil Aviation</i> |
| Catitan <i>Remarks</i> CERTIFICATE ISSUED PURSUANT TO CAR 1996, REGULATION 4(4) AIRCRAFT LEASE EXPIRES ON 30 MARCH 2034 | | |
| NOTA NOTES 1) Tidak apa-apa (jika tulisan atau catitan boleh dibuat dalam perakuan ini kecuali oleh Jabatan Penerbangan Awam. <i>No entries or endorsements may be made in this certificate except by Department of Civil Aviation.</i> 2) Pendaftaran tidak boleh dipindahkan. <i>Registration is not transferable.</i> | | |

Appendix 3: Certificate of Airworthiness

JKP.201 - Pn. 490

| | | |
|--|---|---|
|  MALAYSIA JABATAN PENERBANGAN AWAM DEPARTMENT OF CIVIL AVIATION | | Nombor Perakuan Certificate Number M.1573 |
| PERAKUAN KESELAMATAN TERBANG CERTIFICATE OF AIRWORTHINESS | | |
| Kenegaraan Dan Tanda Pendaftaran <i>Nationality And Registration Marks</i> 9M-LMG | Pembuat dan Nama Sebutan Kapaludera <i>Manufacturer and Manufacturer's Designation of Aircraft</i> ATR – GIE Avions de Transport Regional ATR 72-212 A | Nombor Siri Kapaludera <i>Aircraft Serial Number</i> 1089 |
| Kategori <i>Category</i> TRANSPORT (PASSENGER) | | |
| <p>Perakuan Keselamatan Terbang ini dikeluarkan menurut Konvensyen Penerbangan Awam Antarabangsa bertarikh 7 Disember 1944, dan Akta Penerbangan Awam 1969 dan peraturan-peraturan yang dikeluarkan di bawahnya, untuk kapaludera yang tersebut di atas yang didapati layak untuk terbang jika disenggara dan dikendalikan menurut peraturan-peraturan yang tersebut, dan had-had penerbangan yang bersabit. Manual Penerbangan yang diluluskan oleh Jabatan Penerbangan Awam adalah merupakan sebahagian daripada Perakuan ini.</p> <p><i>This Certificate of Airworthiness is issued pursuant to the Convention on International Civil Aviation dated 7 December 1944, and with the Civil Aviation Act 1969 and regulations issued thereunder, in respect of the above-mentioned aircraft, which is considered to be airworthy if maintained and operated in accordance with the foregoing regulations and the pertinent operating limitations. A Flight Manual approved by the Department of Civil Aviation forms part of this Certificate.</i></p> <div style="text-align: right;">  AIDA NAZLIHA BINTI SAMINGAN b/c Ketua Pengarah Penerbangan Awam for Director General of Civil Aviation </div> <div style="text-align: right;">  </div> | | |
| Catatan <i>Remarks</i> REPLACEMENT OF CERTIFICATE ISSUED ON 02 AUGUST 2013. | | |
| Perakuan ini adalah sah bagi tempoh yang ditunjukkan di bawah ini : <i>This Certificate is valid for the period(s) shown below :</i> | | Tandatangan dan Tarikh <i>Signature and Date</i> |
| Mulai dari : <i>From :</i> | Hingga : <i>To :</i> |  |
| 24/Jul/2014 | 29/Jul/2015 | |
| Mulai dari : <i>From :</i> | Hingga : <i>To :</i> | |
| Mulai dari : <i>From :</i> | Hingga : <i>To :</i> | |
| Mulai dari : <i>From :</i> | Hingga : <i>To :</i> | |

Tiada apa-apa jua tulisan atau catatan boleh dibuat dalam Perakuan ini kecuali oleh Jabatan Penerbangan Awam.
No entries or endorsements may be made in this Certificate except by Department of Civil Aviation.

20103043 - P1848 - K.L.

Appendix 4: Air Operator Certificate

| <div style="text-align: center;">  <div style="display: inline-block; vertical-align: middle;"> <p>MALAYSIA JABATAN PENERBANGAN AWAM DEPARTMENT OF CIVIL AVIATION</p> </div>  </div> | | |
|--|--|---|
| <p>AOC NO. 47</p> | <p style="text-align: center;"><u>OPERATOR NAME</u> MALINDO AIRWAYS SDN. BHD. <small>(010346-W (Company No.)</small></p> | <p>OPERATIONAL POINTS OF CONTACT: Contact details at which operational management can be contacted without undue delay, are listed in: MALINDO AIR OPERATIONS MANUAL Part A Chapter 1.2.3</p> |
| <p>Expiry Date 31-08-2016</p> | <p>Dbal: MALINDO AIR</p> | <p>POINTS OF CONTACT: CAPT. AJMAIN HAKITH (Director of Flight Operations)</p> |
| <p><i>CERTIFICATION I hereby certify that this is a true copy of the AOC No. 47 issued at PUTRAJAYA on 07-09-2015 by The Department of Civil Aviation signed at PUTRAJAYA on 07-09-2015</i></p> <p style="text-align: center;">  CAPT. AJMAIN HAKITH Director General Flight Operations Sector Department of Civil Aviation Malaysia </p> | <p style="text-align: center;"><u>OPERATOR ADDRESS</u> MALINDO AIRWAYS SDN. BHD. C-5-05, BLOCK C, OASIS ARA DAMANSARA, NO. 2, JALAN PJU 1A/7A, ARA DAMANSARA, 47301 PETALING JAYA, SELANGOR.</p> <p>TELEPHONE : +6 03 2035 6699 FAX : +6 03 2035 6698 EMAIL : ajmain.hakith@malindoair.com</p> | <p>TELEPHONE : +6012 3881 354</p> |
| <p>This certificate certifies that</p> <p>MALINDO AIRWAYS SDN. BHD.</p> <p>is authorised to perform commercial air operations under Regulation 24 of the Civil Aviation Regulations 1996 and as defined in the attached operations specifications, in accordance with the Operation Manual.</p> | | |
| <p>Date of Issue: 07-09-2015</p> | <p>Signature : </p> <p>Name : DATU SRI D. AZHARUDDIN B. ABDUL RAHMAN Title : Director General Department of Civil Aviation Malaysia</p> | |

Appendix 5: Lion Air B-Nut Presentation



EXPORT CLASSIFICATION

| Classification | |
|---------------------|-------|
| 1. Canadian ECL(s): | |
| 2. ECCN(s): | |
| 3. P-ECCN(s): | 9E991 |
| 4. USML (ITAR): | |
| 5. P-USML: | |

PROPRIETARY NOTICE

This document is the property of Pratt & Whitney Canada Corp. ("P&WC"). You may not possess, use, copy or disclose this document or any information in it, for any purpose, including without limitation to design, manufacture, or repair parts, or obtain TCCA, FAA, or other government approval to do so, without P&WC's express written permission. Neither receipt nor possession of this document alone, from any source, constitutes such permission. Possession, use, copying or disclosure by anyone without P&WC's express written permission is not authorized and may result in criminal or civil liability.

DISCLAIMER

This document is used for presentation only and it is extracted from Field Report.
This document does not constitute nor replace P&WC Investigation Report, which will be conducted by P&W Service Investigation.

AGENDA

- Reported cracked B-nut events
- Review of investigation results
- Identification of source for hydrogen embrittlement
- Test performed
- Fleet review
- Summary & recommendations

Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 3

CRACKED B-NUT – 3 CASES REPORTED

Malindo (ED0673)



Event: Engine Fire / Fuel Leak
Operator : Malindo, Msn 1089
FN position: #3
Event Date: 28 May 2015
Last FN change: 4 April 2015
PW127M / ED0673, TTSN: 4,865hrs
Engine production: Jan 2013

Wings Air (ED0613)

In Field



Event: Crack observed during maintenance
Operator: Wings Air, Msn 1067
FN position: #11
Event Date: 26 Feb 2015
Last FN change: 26 Feb 2015
PW127M / ED0613, TTSN: 5,103hrs
Engine production: Sep 2012
Note: Manifold transferred to ED0564 for repair during engine shop visit

In Laboratory



Same manifold
Crack in lab. After 3 days
Operator: Wings Air
22 June 2015 – Torqued at 2x EMM
25 June 2015 – cracked observed

Hydrogen embrittlement confirmed on the 3 B-nuts (2 engines)

Export Classification: P-ECCN: 9E991


P&WC Proprietary Information

For Planning Purposes Only 4



INVESTIGATION - LAB RESULTS


Malindo ED0673 (Engine Fire)



Magnified view of the brittle intergranular fracture

Wings Air ED0613 (In Field)

Reddish corrosion products
Suggesting a crack was present
for some time in service



Hydrogen embrittlement
(dimple caused by hydrogen
pressurising grain)



T fitting general condition (opposite side)


LAB RESULTS – ED0613 – CRACKED IN LAB

Laboratory analysis was performed on ED0613 manifold in order to duplicate the failure. Higher torque (twice the one recommended in EMM) was applied to manifold and crack was observed few days after application.




Corrosion Products in thrust Wire recess

Presence of reddish corrosion products suggesting crack present prior torque test



Typical "fisheyes" consistent with hydrogen embrittlement



Fracture surface near external edge
Absence of corrosion products on this portion

Higher corrosion level inside, suggesting corrosion progressed from inside out



Surface corrosion Condition is typical for all T fittings on this manifold


June 22 – Installation (2X recommended Tq)
June 23 – No crack
June 24 – Holiday (no inspection)
June 25 – Crack observed


P&WC recommended immediate removal of other 2 manifolds on engine ED0613

Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 7






Pratt & Whitney Canada
A United Technologies Company

Identification of source for hydrogen embrittlement

ENGINES
SUPPORT
INNOVATION
PEOPLE

FISHBONE – HYDROGEN EMBRITTLEMENT



Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 9

SUPPLY CHAIN REVIEW

Supplier process/quality review

| | Modification to | | | | | |
|---------------------|-----------------|-----------|---------|------------|-------------|-------------------|
| | Location | Equipment | Process | Inspection | Consumables | QN (Mat'l defect) |
| Manifold Assembly | N | N | Y* | N | N | N |
| B-Nut Manufacturing | N | N | N | N | N | N |

*Additional pre-torquing task added in 2014

Modifications introduced with the phase 4 fuel nozzle

No consumables used at this operation

Introduced after the manufacturing of ED0613/ED0673 manifolds

No other changes in the last 10 years

Quality Notifications (QN) reviewed for manifolds and B-nuts

No Q/N's related to H.E. or material defect


Leak at test, tool mark, damage on hose (porosity, tear, cut)

Export Classification: P-ECCN: 9E991


P&WC Proprietary Information

For Planning Purposes Only 10


MANIFOLD ASSEMBLY PROCESS



MANIFOLD ASSEMBLY PROCESS



MANIFOLD ASSEMBLY PROCESS




Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 13

B-NUT MANUFACTURING PROCESS



Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 14

PRODUCTS USED DURING MANUFACTURING OF MANIFOLDS

List of products used during manifold manufacturing/assembly

| Product Name | Product Type | Details | B-Nut | Manifold | Source for H.E |
|--------------|----------------------|---|-------|----------|----------------|
| Excelcut 429 | Cutting oil | recommended for stainless steel manufacturing | X | | Unlikely |
| Triklone LE | Trichloroethylene | Vapor degreaser Highly volatile | X | | No |
| P-80 | Rubber lubricant | Alkaline (Ph 8.4) | | X | No |
| | De-mineralized water | | | X | No |
| Isopar K | Hydrotreated naphita | Petroleum solvent (Varsol) | | X | No |

Same products/process used for over 10 years

Over 1,606 new engines produced (Over 47,000 nuts)

Excelcut 429

Chemical composition not fully known (proprietary)

Over 10 years of usage at B-nut machining


P&WC will be conducting tests on Excelcut 429

Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 15

B-NUT PRODUCTION REVIEW



Export Classification: P-ECCN: 9E991


P&WC Proprietary Information

For Planning Purposes Only 16

REPAIR & OVERHAUL

Minor repair per EMM, 72-01-00

Limited to fire retardant protection
Manifolds did not receive this repair



Major repair

Proprietary repair to HS-Marston
No cracked B-nut were received for repair

| | Last 12 Months | Last 5 Years | Last 9 Years |
|-----------------|----------------|--------------|--------------|
| 3059764-01 (7) | 58 | 232 | 235 |
| 3059765-01 (8) | 21 | 201 | 206 |
| 3059766-01 (11) | 76 | 389 | 594 |
| Total: | 155 | 822 | 1035 |

Only B-nut crack known case is the manifold received from Lion Group

Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 17



 **Pratt & Whitney Canada**
A United Technologies Company

Fleet Review

ENGINES

SUPPORT


INNOVATION

PEOPLE

FLEET INSPECTION FOR CORROSION PITS

| | | >ED0300 | >ED0375 | >ED0450 | >ED0525 | >ED0600 | >ED0675 | >ED0750 | >ED0825 | >ED0900 | >ED0975 | >ED1050 |
|-------------------------|-----|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|
| | All | <=ED0300 | <=ED0375 | <=ED0450 | <=ED0525 | <=ED0600 | <=ED0675 | <=ED0750 | <=ED0825 | <=ED0900 | <=ED0975 | <=ED1050 |
| LionAir Group | | | | | | | | | | | | |
| Excluded | 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 10 | 2 |
| No Corrosion | 53 | 7 | 1 | 3 | 1 | 3 | 3 | 9 | 7 | 10 | 0 | 0 |
| Corrosion | 41 | 9 | 7 | 4 | 4 | 7 | 6 | 2 | 1 | 0 | 0 | 0 |
| All | 110 | 16 | 8 | 7 | 5 | 10 | 9 | 11 | 8 | 10 | 14 | 2 |
| Ratio (corrosion) | 44% | 56% | 88% | 57% | 80% | 70% | 67% | 18% | 13% | 10% | 0% | -- |
| World Wide Fleet | | | | | | | | | | | | |
| No Corrosion | 63 | 28 | | | | 5 | 14 | 6 | 1 | 3 | 5 | 1 |

World Wide Fleet inspection
9 operators
63 engines inspected
No report of corrosion pits



Typical condition of manifolds inspected at other operators

Applying the Lion Air Group ratio to other operators would result in 27 engines

Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 19

FLEXIBLE MANIFOLDS DESIGN AND IN-SERVICE EXPERIENCE

Design

B-nut design within existing P&WC design experience



Flexible Manifold Conf. (Post-SB21705) - 43 detail parts

Field Experience

| PW127 with Flexible (Nov 1999) | |
|---|-------------|
| Engine produced with flexible manifolds | 1,740 |
| Total Fleet hours | Over 15M |
| Fleet leader engine | 35,500hrs |
| Estimated No. of FN change | Over 15,000 |


Other Models

| Model | Qty Produced | Fleet hours (M) |
|--------|--------------|-----------------|
| PW150A | 1141 | 12.5 |
| PW901 | 924 | 31.2 |
| PW980 | 224 | 7 |

Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 20



TORQUE TEST – PERFORMED AT P&WC



Tests performed to validate design margin

B-nut inspected per FPI. No crack found

EMM torque limit: 250-270 lb-in



Nut & Crowfoot condition after 1320 lb-in



Cracked B-nut reported by Lion Air

Unable to replicate observed failure mechanism, overtorque ruled out

REVIEWS AT MALINDO & LION AIR

Fuel Nozzle Process Review performed on June 18 and 19

Questions raised during process review:

- Use of a Cee Bee product
- Use of Electrical Contact Cleaner (CRC, C&C) to "cool down" the nuts before FNZ change
- Leak detector check with local solution instead of recommended product

Cee Bee products and Hand soap returned to MTL for Lab analysis on (on-going)

No cracks observed to date

P&WC Material specialist confirmed products would not cause Hydrogen Embrittlement

C & C cleaner analyzed in Indonesia lab

Lab results indicates many chemicals containing hydrogen

Unclear if chemicals can contribute to Hydrogen Embrittlement

High level of variability for mix of products, concentration and temperature

Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 23

P&WC EXPERIENCE



Pratt & Whitney Canada
A United Technologies Company

S.I.L. NO. PT6A-214

SERVICE INFORMATION LETTER

Subject Use of non approved cleaning product on fuel nozzle tips

Applicability All PT6A Large Engines

Reference N/A

This Service Information Letter (SIL) is issued to inform all operators and maintenance providers of the importance of using only those cleaning products defined in the relevant P&WC engine maintenance manual to clean PT6 fuel nozzle tips. An ongoing investigation has revealed that a certain repair service provider used by a customer was using Mirachem 250, which is not called up in the P&WC maintenance manuals for this operation. In fact, this cleaning solution is not considered fully compatible with the base material of the fuel nozzles and tips. In order to prevent any possible damage to the fuel nozzle tips, such practice must be discontinued. In the mean time, no other action is required other than P&WC's recommendation that operators or their repair supplier does not use Mirachem 250 or any other products not specifically defined in the P&WC maintenance manual.

Additionally, for PT6's engines equipped with Duplex type fuel nozzle tips, we remind operators you that it is not an acceptable practice to remove and re-install fuel nozzle tips without processing the tips through the overhaul level workscope. Install only overhauled or new nozzle tips when processing fuel nozzles.

For further information, please contact your local P&WC Field Support Representative, or the P&WC Customer Help Desk, Tel: +1 452-647-8000 or +1-800-258-8000. We can also be reached at chrt@pwc.ca, or our website www.pwc.ca.

Pascale Benoit-Lapointe

Pascale Benoit-Lapointe
Customer Service



This Service Information Letter is valid until superseded or cancelled by revision

EXPORT CONTROL CLASSIFICATION: This document does not contain technical data.
ISSUED: October 14/2013

Page 1 of 1



PRATT & WHITNEY CANADA CORP.
WILKES-BOE, CONNECTICUT, U.S.A.
CANADA, INC. (C)
REGISTERED IN CANADA

P&WC Proprietary Information

For Planning Purposes Only 24

Mirachem 250 on PT6A engine

Used during maintenance

Causing hydrogen embrittlement

Product advertised as non acidic and safe for stainless steel by manufacturer

Review of MSDS presence of phosphoric acid up to 10%

TESTING OF PRODUCTS



CEE BEE 280 / Torque at 600 lbs-in



Super BEE 210 / Torque at 600 lbs-in



Hand Soap / Torque at 600 lbs-in

P&WC received 3 products

2 B-nuts exposed to each product

B-nut torqued at 600 lbs-in

Test initiated on July 22nd

No B-nut cracked

Test procedure formalized

Further tests to be conducted on

Mirachem 250 - In process

Excelcut 429 - Material in procurement

C&C cleaner - Shipping hardware to Indonesia


Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 25



INVESTIGATION SUMMARY



Challenges


- Source of Hydrogen Embrittlement (H.E.) not identified
- No methods available to segregate manifold affected to H.E.
- No repair possible for parts affected by H.E.
- H.E. causes sudden failure of parts when under stress

Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 27

RISK ASSESSMENT / PRIORITY



Priority levels

- Per risk assessment
- At aircraft level
- Following SI 71-2015 results

P&WC recommendations

- Follow EMM instructions
- Perform SI 71-2015
- Replace manifolds potentially exposed to H.E.

Current status

- 9 engines upgraded
- 16 engines considered not exposed
- 41 engines with corrosion

Assumptions:

- Fleet exposure initiated Jul '14
- "Fast" population – corrosion on T fittings
- "Slow" population – no corrosion on T fittings
- Ratio of 41 "fast" out of 94 total affected
- 3 B-nut fractured events considered

| Priority | | | No. of engines | Upgraded |
|----------|--|-------------------------------------|----------------|----------|
| Level | Description | Recommendation | | |
| 1 | A/C with both engines showing signs of corrosion | Replace one engine set within 100FH | 16 | 0 |
| 2 | A/C with one engine showing signs of corrosion | Replace engine set within 200FH | 24 | 1 |
| 3 | A/C with no engine showing signs of corrosion | Replace by Oct 15th | 27 | 0 |
| 4 | Remaining engines + spares | Replace by Nov 30th | 27 | 0 |
| N/A | Engine without any FN change | | 16 | |

As of August 21st, 2015

Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 28

CONCLUSION

Production/quality issue can be ruled out as a source for B-Nut cracking

Source of contamination / corrosive agent is still undetermined
P&WC and Lion Group are still conducting testing

Replacement of all manifolds potentially exposed by the end of November


Need to coordinate logistics to accelerate rejuvenation
Custom clearance, point of use shipment

P&WC is fully committed to support
Training, assisting maintenance crew, parts and commercial support

Export Classification: P-ECCN: 9E991

P&WC Proprietary Information

For Planning Purposes Only 29



Appendix 6: Pratt & Whitney Service Information Letter

SERVICE INFORMATION LETTER

WARNING - PROPRIETARY RIGHTS NOTICE

This document is the property of Pratt & Whitney Canada Corp. ("P&WC"). You may not possess, use, copy or disclose this document or any information in it, for any purpose, including without limitation to design, manufacture, or repair parts, or obtain FAA or other government approval to do so, without P&WC's express written permission. Neither receipt nor possession of this document alone, from any source, constitutes such permission. Possession, use, copying or disclosure by anyone without P&WC's express written permission is not authorized and may result in criminal or civil liability.

Subject Use of non-approved product on PW100 Flexible Manifold

Applicability PW100 Engines with flexible fuel nozzle manifolds

This Service Information Letter ("SIL") is revised to provide the final conclusions on the associated investigation.

P&WC investigated two cases of flexible manifold B-nut reported cracked (Ref. Figure 1). Both cases were reported by the same operator group and the review of the material confirmed hydrogen embrittlement.

Hydrogen embrittlement occurs when hydrogen diffuses into the metal. It changes the material properties and the exposed metal becomes brittle. In the case of the flexible manifold, the B-nut may become susceptible to cracking in service, thus potentially causing an external fuel leak. The fractured surfaces analyzed by P&WC show no signs of a crack propagating by fatigue and suggests a sudden fracture mechanism.

Corrosion attacks and pits on the B-nut surface and the T fittings (Ref. Figure 2) was also observed. It is believed that the observed condition resulted from exposing the material to an aggressive product, likely acidic. In some cases, the corrosion pits showed a reddish appearance (Ref. Figure 1) that can be more or less visible (Ref. Figure 2). It is also possible that corrosion pits are not observed on B-nut affected by hydrogen embrittlement.



Figure 1 : Cracked B-nut

This Service Information Letter is valid until superseded or cancelled by revision.

| Export Control Classification | | | (X) if Applicable |
|--|-------------|-------------|-------------------|
| Contains no Technical Data | | | (X) |
| Not Subject to the EAR pursuant to 15 CFR 734.7(a)(1) or Not Subject to the ITAR pursuant to 22 CFR 120.11 (NSR) | | | () |
| Jurisdiction and Classification based on Physical Location of the Item. | Location | Regulations | |
| | Outside US* | EAR | ITAR |
| | U.S. | | |
| | | EUPA (ECL) | DPA (CG) |
| | Canada | | |

ISSUED: 06/30/2015
REVISED: 06/01/2016

Page 1 of 2

PRATT & WHITNEY CANADA CORP.
MARIEVILLE, QUEBEC
CANADA J8G 1A1
PRINTED IN CANADA

PRATT & WHITNEY CANADA
SERVICE INFORMATION LETTER

S.I.L NO. PW100-169R1

P&WC was able to replicate the above observations and the distress by hydrogen embrittlement via exposing the B-nut to a chloride acid (HCl) solution while the B-nut was under tension load. P&WC selected chloride acid for the tests as this acid is well known to liberate hydrogen and it was expected to get results rapidly.

However, any product or any chemical reaction between two or more products liberating hydrogen may lead to hydrogen embrittlement. For the reported events, the product that caused hydrogen embrittlement has not been identified. The investigation concluded however that the B-nuts were exposed to an acidic product while installed on the engine.

P&WC would like to remind all customers of the importance to use the products recommended in the Engine Maintenance Manual "EMM" (Ref. 72-01-40, FUEL SYSTEM) for fuel nozzles and fuel manifolds removal, installation and cleaning. P&WC also confirms that all products approved by P&WC and listed in the EMM will not cause Hydrogen Embrittlement.

There is no inspection available in the field to identify manifolds affected by hydrogen embrittlement. Additionally, it is not possible to predict the remaining life of B-nuts affected by this condition as it depends of many parameters, notably, the aggressiveness of the product and the exposure time. Therefore, any manifold suspected to have been exposed to an acidic product or any other product suspected to liberate hydrogen should be removed from service immediately.




Figure 2 : Corrosion pits (left B-nut / Right T-fitting)

Yours, Truly,

PRATT & WHITNEY CANADA CORP

Daniel Gagnon
Customer Engineering
PW100 Engine Program

Vincent St-Pierre
Manager, Customer Engineering
PW100 Engine Program

This Service Information Letter is valid until superseded or cancelled by revision.

P&WC Proprietary Information. Subject to restriction on first page.

The export control classification with respect to this document is contained on the first page

ISSUED: 06/30/2015

REVISED: 06/01/2016

Page 2 of 2

PRATT & WHITNEY CANADA CORP.
SARASOTA, FL 34234
QUEBEC, CANADA J2G 1A1
PRINTED IN CANADA

Appendix 7: Malindo Air Quality Notice



www.malindoair.com

Ref : MAQA/QN/ATR72/16/04
Date : 12 February 2016

QUALITY NOTICE

TITLE : FUEL NOZZLE RESTORATION OF PW127M (ATR 72-600)

1. INTRODUCTION/BACKGROUND.

- 1.1 It was reported of incident of engine fire involving Malindo Air PW127M engines installed on ATR 72-600.
- 1.2 A thorough investigation lead by Pratt & Whitney Canada team has been performed and as a result of the investigation, it was found that the engine fire was due to fuel nozzle B-nut crack (**refer appendix**).
- 1.3 In conclusion to this finding, it was found that the B-nut cracking was due to hydrogen embrittlement. In theory, hydrogen embrittlement may occur with existence of the following elements:
 - 1.3.1 Time
 - 1.3.2 Material Susceptibility
 - 1.3.3 Tensile Stress
 - 1.3.4 Source of hydrogen (acidic product/solution)
- 1.4 PW127M B-nut is made from stainless steel (17-4PH – hardened to H1075) which is in intermediate range of susceptibility. With the presence of acidic product onto the material whilst it is under tensile stress (torque) has created a condition susceptible for hydrogen embrittlement (**refer appendix**). With sufficient time for the hydrogen to react with the material, the material then become brittle thus causing it to crack/break.

2. ACTIONS

From this, Quality Assurance has outlined several mitigating action to minimize any possibilities of maintenance lapses.

- 1.4.1 All task involving removal and installation (restoration) of PW127M fuel nozzle is considered as crucial and critical to engine propulsion and aircraft safety. Thus, a **duplicate inspection** is required whenever above task is involved.
- 1.4.2 In addition, restoration of fuel nozzle for both PW127M engines on one aircraft **shall not be performed** at the same maintenance visit .

a member of **Lion Group**

C-5-05, Block C, Oasis Ara Damansara, 2 Jalan PJU 1A/7A, 47301 Petaling Jaya, Selangor, Malaysia
www.malindoair.com E-mail: info@malindoair.com Tel: +603-7075 8888 Fax: +603-7075 8888 Call Centre: +603-7661 5248



www.malindoair.com

- 1.4.3 It is crucial for the engineer in-charge to perform a detailed inspection of the manifold hoses B-nut to ensure no **early sign of corrosion** is observed. A manifold with sign of corrosion shall be quarantined and reported to Quality Assurance for further investigation.
- 1.4.4 Licensed Engineer shall ensure that **only approved solvent/materials** listed in Maintenance Manual are to be used throughout the maintenance process.

Please be guided accordingly. Thank You


General Manager Quality Assurance



a member of **Lion Group**

C-5-05, Block C, Oasis Ara Damansara, 2 Jalan PJU 1A/7A, 47301 Petaling Jaya, Selangor, Malaysia
www.malindoair.com E-mail: info@malindoair.com Tel: +603-2035 8888 Fax: +603-2035 8898 CSE Hotline: 03-7841 5188

APPENDIX



Image above shows one of the findings of B-nut crack.

Malindo ED0673 (Engine Fire)



Image above shows magnified view of brittle intergranular fracture confirming on Hydrogen embrittlement.

a member of **Liaa Group**

C-5-05, Block C, Oasis Ara Damansara, 2 Jalan PJU 1A/7A, 47301 Petaling Jaya, Selangor, Malaysia
www.malindoair.com E-mail: info@malindoair.com Tel: +603-9035 8698 Fax: +603-9035 8698 Call Centre: +603-7841 5098