



SI 13/15



Date : 26 October 2015
Type : Viking DHC6-400
Registration : 9M-SSD
Operator : MASwings
Fatality : 0
Nature : Aircraft veered off runway on landing
Location : Mukah Airport, Sarawak

SUMMARY

During touchdown in Mukah Airport (MKM), the aircraft landed positively on the main wheels. However, the crew noticed that the aircraft bank to the left. The aircraft's centerline was maintained by using the rudder and Beta range was selected upon contact of the nose wheel with the runway. The aircraft drifted to the left as it decelerated. The crew tried to correct the situation by applying the brake but the aircraft continue to drift to the left side of the runway. The crew applied more pressure on the brakes and eventually the aircraft skidded on the runway and come to a stop. After verification with the airfield attendant that the aircraft only suffered a deflated left main wheel, the crew decided to disembark the passenger on the runway as the aircraft was immobilised. There were no injuries being reported by the crew and passengers.

CAUSE

Undetermined.

SAFETY RECOMMENDATIONS

Nil.