



SI 02/16



Date : 8 January 2016
Type : CL605
Registration : 9M-ATM
Operator : Hornbill Skyways
Fatality : 0
Nature : Aircraft wing collided with hangar pillar
Location : Kuching International Airport, Sarawak

SUMMARY

Not available..

CAUSE

Not available.

SAFETY RECOMMENDATIONS

Not available.

Note: Occurrence categorised as MOR.