



SI 12/15



Date : 15 September 2015
Type : PA28-161
Registration : 9M-NKF
Operator : APFT
Fatality : 0
Nature : Aircraft veered off runway on landing
Location : Kota Bharu Airport, Kelantan

SUMMARY

A cadet pilot has flown PA28 (9M-NKF) for his second solo circuit sortie on 15 September 2015. The took off at time 1615LT and for intention of 2 circuits and landing. He was able to make a safe landing on the first circuit and took off for the other one. For the second circuit, he was instructed to hold on downwind thereafter being cleared for approach. He make a normal approach and able to land on Runway 10. During the landing roll, trainee found that his slightly right of the centerline and try to make correction. He pressed left rudder and suddenly aircraft veered to the left and skidded out of the runway and stopped into the drain.

CAUSE

Undetermined.

SAFETY RECOMMENDATIONS

It is recommended that:

1. Instructors and cadets must aware of surface wind condition before going for solo or dual sorties.
2. Expose cadets with crosswind technique for take-off and landing.