



SI 07/15



Date : 8 July 2015  
Type : DHC6-400  
Registration : 9M-SSD  
Operator : MASwings  
Fatality : 0  
Nature : Collision on ground  
Location : Mukah Airfield, Sarawak

### **SUMMARY**

Flight MH3415 from Mukah to Kuching landed safely at Mukah Airfield. Thereafter instructed by the airfield attendant to park the aircraft at the north eastern coener of the apron, near to the yellow line, as to give way to incoming VVIP aircraft. The crew followed the instruction that was given by the airfield attendant and the parking position of the aircraft was agreed by the airfield attendant.

The event happened when aircraft registration N639TS, taxiing in for the apron to drop off the VVIP. The aircraft was taxiing in and marshaled by their own personnel. The port wing of the aircraft struck the nose of 9M-SSD on the starboard side. The event was seen by MASwings Captain at the terminal. From the Captain's observations, N639TS was being on the left of centerline when it happens.

### **CAUSE**

Undetermined.

### **SAFETY RECOMMENDATIONS**

Undetermined.