



SI 11/15



Date : 27 August 2015
Type : DHC6-400
Registration : 9M-SSB
Operator : MASwings
Fatality : 0
Nature : A/craft veered off runway on landing
Location : Marudi Airport, Sarawak

SUMMARY

MASwings Viking DHC6-400 Twin Otter aircraft operated MH3568 from Miri Airport (MYY) to Marudi Airport (MUR) on 27 August 2015. The aircraft was stable with both main wheel on touch down at Runway 10, however as the nose wheel contacted the runway surface, the aircraft veered to the left uncontrollably.

The crew applied the right rudder and brake but unable to stop the aircraft movement. Shortly after that, the crew tried to maneuver the aircraft by giving input to the steering and it was unsuccessful to steer the aircraft. The aircraft came to a complete stop on the unpaved field at the left side of the runway. The engines were shut down as per normal procedure. The crew and passengers were uninjured.

CAUSE

Undetermined.

SAFETY RECOMMENDATIONS

Nil.