

AAIB Malaysia Accident/Serious Incident Notification Form

Ref No MOT/BSKU(S)600 **A 01/18**

Ministry of Transport Malaysia

(Air Accident Investigation Bureau)

No 26, Jalan Tun Hussein,

Presint 4, 62100 Putrajaya,

Telephone: +603 8892 1071
Facsimile: +603 8888 0163
Website: www.mot.gov.my
Email: yahaya@mot.gov.my

Malaysia				
A. Classification accident / Incident (Serious) / Incident (Minor)	ACCID	INCID (Serious)	INCID	
B. Detail of Aircraft / Flight	Manufacturer Model Nationality Registration Flight Number Serial Number	: CIRRUS DESIGN CORPORATION : SR20 : MALAYSIA : 9M-ZWR : - : 1894		
C. Detail of Owner / Operator / Lessee (If applicable)	Owner Lessee (If Applicable) Operator	: TWIN TURBO EN : - : TWIN TURBO	TERPRISE	
D. Date and Time (Local / UTC) of the event i.e. accident or serious incident	Date Time	: 01.02.2018 : 1251HRS (LOCAL	TIME)	
E. Last point of departure and point of intended landing of the aircraft	Last point of departure Point of intended landing	: SENAI / WMKJ : TIOMAN / WMBT		
F. Last known position	Latitude: N2° 48'53.4600" Longitude: E104° 9'29.0448" Descriptions Aircraft end up approximately end of RWY 20 at right hand side, on the grass.			

	T				
G. No of crew and passengers; aboard, killed and seriously injured	Pilot : 0 Crew :- Passenger : 0 Conditions Pilot managed to evacuate	01 03	v and without a	ov injuries	
II Ovalification of the	Pilot managed to evacuate all passengers safely and without any injuries. Pilot in Command qualification: CPL 1/R				
H. Qualification of the pilot in command and nationality of the crew and passengers	Pilot in Command qualification : CPL 1/R				
	Pilot in Command nationality : MALAYSIAN				
	First Officer nationality : -				
	Passengers nationality	: MALAYSIAN	I		
I. Description of the accident or serious incident and the extent of damage to the aircraft so far as is known:	Aircraft skidded to the right and hit the fence. Damages as below: 1. Nose wheel and left main wheel collapsed. 2. Both wings leading edge broken. 3. Prop strike and prop spinner dented. 4. Minor scratchers on the fuselage.				
J. An indication to what extent the investigation will be conducted or is proposed to be delegated by the State of Occurrence	The Air Accident Investigation Bureau (Malaysia) has classified this as an Accident and has conducted an investigation in accordance with the provision of Annex 13 to the Convention of International Civil Aviation.				
K. Presence and description of dangerous goods on board the aircraft	No Yes (Please describe) Unknown			Unknown	
L. Operation Type	Commercial Aviation	Scheduled	Passenger		
	General Aviation	Non Scheduled	Cargo		
	Others		Others		
M. Level of damage to aircraft (If information is available)	Destroyed <u>Substant</u>	tial Minor	None	Unknown	

The State of Occurrence shall forward a notification of an accident or serious incident with a minimum of delay and by the most suitable and quickest means available to: a) the State of Registry b) the State of the Operator c) the State of Design d) the State of Manufacture and e) the International Civil Aviation Organisation, when the aircraft involved is of a maximum mass of over 2250 kg.

BSKU/Notification Form/Issue 1 Rev Initial